



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

SEP 9 - 2008

MR. HARRY KON
ACCOUNT MANAGER
K2 MOTOR CORPORATION
250 BENTON CT.
WALNUT, CA 91789

NVS-215kjs
08E-050

SUBJECT: FMVSS 108/HEADLAMPS/MISSING AMBER SIDE REFLECTORS

DEAR MR. KON:

This letter serves to acknowledge K2 Motor Corporation's (K2 Motor) notification to the National Highway Traffic Safety Administration (NHTSA) of a safety noncompliance with Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment," in the products described below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

See the attached document

NHTSA Campaign Number: 08E-050

Mfg's Report Date: August 4, 2008

Components: FMVSS 108/HEADLAMPS/MISSING AMBER SIDE REFLECTORS

Potential Number of Units Affected: 1,921

Summary:

K2 MOTOR IS RECALLING 1,921 AFTERMARKET HEADLAMPS OF VARIOUS MODELS SOLD FOR USE ON THE ATTACHED LISTED VEHICLES. THESE HEADLAMPS ARE MISSING THE AMBER SIDE REFLEX REFLECTOR WHICH FAILS TO CONFORM WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 108, "LAMPS, REFLECTIVE DEVICES, AND ASSOCIATED EQUIPMENT."

Consequence:

WITHOUT THE AMBER SIDE REFLEX REFLECTORS, THE LIGHTING VISIBILITY MAY BE AFFECTED, POSSIBLY RESULTING IN A VEHICLE CRASH.

Remedy:

K2 MOTOR WILL NOTIFY OWNERS AND OFFER A FULL REFUND. THE RECALL IS EXPECTED TO BEGIN DURING SEPTEMBER 2008. OWNERS MAY CONTACT K2 MOTOR AT 1-909-839-2992.

Notes:

THIS RECALL ONLY PERTAINS TO AFTERMARKET REPLACEMENT EQUIPMENT AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON VEHICLES MANUFACTURED BY HONDA, FORD, OR CHRYSLER. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

This recall is the result of an investigation, OA-108-071221A, conducted by the Office of Vehicle Safety Compliance.

Please provide the following additional information and be reminded of the following requirements:


We have received K2 Motor's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete. Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

K2 Motor must file a sample of the envelope which you intend to use to mail the recall notice to owners. The words "SAFETY", "RECALL", "NOTICE" in any order must be printed on the envelope in larger font than the customers name and address.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227, by email at Kelly.Schuler@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

A handwritten signature in black ink, appearing to read "G. Person", with a long horizontal flourish extending to the right.

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement

Enclosure

08E505	Make	Model	Model Year
1	CHEVROLET	C10	1994
2	CHEVROLET	C10	1995
3	CHEVROLET	C10	1996
4	CHEVROLET	C10	1997
5	CHEVROLET	C10	1998
6	CHEVROLET	CAVALIER	2000
7	CHEVROLET	CAVALIER	2001
8	CHEVROLET	CAVALIER	2002
9	CHEVROLET	PICKUP	1994
10	CHEVROLET	PICKUP	1995
11	CHEVROLET	PICKUP	1996
12	CHEVROLET	PICKUP	1997
13	CHEVROLET	PICKUP	1998
14	CHEVROLET	S10	1982
15	CHEVROLET	S10	1983
16	CHEVROLET	S10	1984
17	CHEVROLET	S10	1985
18	CHEVROLET	S10	1986
19	CHEVROLET	S10	1987
20	CHEVROLET	S10	1988
21	CHEVROLET	S10	1989
22	CHEVROLET	S10	1990
23	CHEVROLET	S10	1991
24	CHEVROLET	S10	1992
25	CHEVROLET	S10	1993
26	CHEVROLET	SILVERADO	1999
27	CHEVROLET	SILVERADO	2000
28	CHEVROLET	SILVERADO	2001
29	CHEVROLET	SILVERADO	2002
30	CHEVROLET	SILVERADO	2003
31	CHEVROLET	SILVERADO	2004
32	CHEVROLET	SILVERADO	2005
33	CHEVROLET	SILVERADO	2006
34	CHEVROLET	SILVERADO	2007
35	CHEVROLET	SILVERADO	2008
36	CHEVROLET	VENTURE	1997
37	CHEVROLET	VENTURE	1998
38	CHEVROLET	VENTURE	1999
39	CHEVROLET	VENTURE	2000
40	CHEVROLET	VENTURE	2001
41	CHEVROLET	VENTURE	2002
42	CHEVROLET	VENTURE	2003
43	DODGE	NEON	2000
44	DODGE	NEON	2001
45	DODGE	NEON	2002
46	DODGE	NEON	2003
47	DODGE	NEON	2004
48	DODGE	RAM	1994
49	DODGE	RAM	1995
50	DODGE	RAM	1996
51	DODGE	RAM	1997

52	DODGE	RAM	1998
53	DODGE	RAM	1999
54	DODGE	RAM	2000
55	DODGE	RAM	2001
56	FORD	F150	1997
57	FORD	F150	1998
58	FORD	F150	1999
59	FORD	F150	2000
60	FORD	F150	2001
61	FORD	F150	2002
62	FORD	F150	2003
63	FORD	FOCUS	2000
64	FORD	FOCUS	2001
65	FORD	FOCUS	2002
66	FORD	FOCUS	2003
67	FORD	FOCUS	2004
68	FORD	FOCUS	2005
69	FORD	FOCUS	2006
70	FORD	FOCUS	2007
71	FORD	FOCUS	2008
72	FORD	MUSTANG	1987
73	FORD	MUSTANG	1988
74	FORD	MUSTANG	1989
75	FORD	MUSTANG	1990
76	FORD	MUSTANG	1991
77	FORD	MUSTANG	1992
78	FORD	MUSTANG	1993
79	FORD	MUSTANG	1994
80	FORD	MUSTANG	1995
81	FORD	MUSTANG	1996
82	FORD	MUSTANG	1997
83	FORD	MUSTANG	1998
84	FORD	MUSTANG	1999
85	FORD	MUSTANG	2000
86	FORD	MUSTANG	2001
87	FORD	MUSTANG	2002
88	FORD	MUSTANG	2003
89	FORD	MUSTANG	2004
90	FORD	RANGER	1993
91	FORD	RANGER	1994
92	FORD	RANGER	1995
93	FORD	RANGER	1996
94	FORD	RANGER	1997
95	GMC	PICKUP	1994
96	GMC	PICKUP	1995
97	GMC	PICKUP	1996
98	GMC	PICKUP	1997
99	GMC	PICKUP	1998
100	GMC	SIERRA	1988
101	GMC	SIERRA	1989
102	GMC	SIERRA	1990
103	GMC	SIERRA	1991

104	GMC	SIERRA	1992
105	GMC	SIERRA	1993
106	HONDA	ACCORD	1990
107	HONDA	ACCORD	1991
108	HONDA	ACCORD	1992
109	HONDA	ACCORD	1992
110	HONDA	ACCORD	1993
111	HONDA	ACCORD	1994
112	HONDA	ACCORD	1995
113	HONDA	ACCORD	1996
114	HONDA	ACCORD	1997
115	HONDA	ACCORD	1998
116	HONDA	ACCORD	1999
117	HONDA	ACCORD	2000
118	HONDA	ACCORD	2001
119	HONDA	ACCORD	2002
120	HONDA	ACCORD	2003
121	HONDA	CIVIC	1990
122	HONDA	CIVIC	1991
123	HONDA	CIVIC	1992
124	HONDA	CIVIC	1993
125	HONDA	CIVIC	1994
126	HONDA	CIVIC	1995
127	HONDA	CIVIC	1996
128	HONDA	CIVIC	1997
129	HONDA	CIVIC	1998
130	HONDA	CIVIC	1999
131	HONDA	CIVIC	2000
132	HONDA	CIVIC	2001
133	HONDA	CIVIC	2002
134	HONDA	CIVIC	2003
135	HONDA	CRX	1990
136	HONDA	CRX	1991
137	HONDA	PRELUDE	1992
138	HONDA	PRELUDE	1993
139	HONDA	PRELUDE	1994
140	HONDA	PRELUDE	1995
141	HONDA	PRELUDE	1996
142	K2 MOTOR	LBACD90YD	9999
143	K2 MOTOR	LBACD92YD	9999
144	K2 MOTOR	LBACD94JMYD	9999
145	K2 MOTOR	LBACD94YD	9999
146	K2 MOTOR	LBACD96JMYD	9999
147	K2 MOTOR	LBACD96YD	9999
148	K2 MOTOR	LBBEE98YD	9999
149	K2 MOTOR	LBC1094YD	9999
150	K2 MOTOR	LBCRX90JYMD	9999
151	K2 MOTOR	LBCRX90YD	9999
152	K2 MOTOR	LBCV88JMYD	9999
153	K2 MOTOR	LBCV88YD	9999
154	K2 MOTOR	LBCV90JMYD	9999
155	K2 MOTOR	LBCV90YD	9999

156	K2 MOTOR	LBF0C00KS	9999
157	K2 MOTOR	LBLIB02KS	9999
158	K2 MOTOR	LBMAX95JMKS	9999
159	K2 MOTOR	LBMAX95KS	9999
160	K2 MOTOR	LBMIN02KS	9999
161	K2 MOTOR	LBMST87JMKS	9999
162	K2 MOTOR	LBMST87KS	9999
163	K2 MOTOR	LBNEO00KS	9999
164	K2 MOTOR	LBPIK89KS	9999
165	K2 MOTOR	LBPL924PCYD	9999
166	K2 MOTOR	LBPL92JM4PCYD	9999
167	K2 MOTOR	LBS1082KS	9999
168	K2 MOTOR	LBSIV04JMYD	9999
169	K2 MOTOR	LBSIV04YD	9999
170	K2 MOTOR	LBSIV99JMYD	9999
171	K2 MOTOR	LBSIV99YD	9999
172	K2 MOTOR	LCAD94YD	9999
173	K2 MOTOR	LCCAV00KS	9999
174	K2 MOTOR	LCCOR93JMKS	9999
175	K2 MOTOR	LCCOR93KS	9999
176	K2 MOTOR	LCCOR98KS	9999
177	K2 MOTOR	LCCV903JMDY	9999
178	K2 MOTOR	LCG1G3DY	9999
179	K2 MOTOR	LCG1G3JMDY	9999
180	K2 MOTOR	LCG2G4JMYD	9999
181	K2 MOTOR	LCG2G4YD	9999
182	K2 MOTOR	LCGMC88APC	9999
183	K2 MOTOR	LCMST95JMDY	9999
184	K2 MOTOR	LCMST95YD	9999
185	K2 MOTOR	LCPIK92KS	9999
186	K2 MOTOR	LCRAM94YD	9999
187	K2 MOTOR	LCRAN93JMAPC	9999
188	K2 MOTOR	LCTCAM95KS	9999
189	K2 MOTOR	LCTEMR95JMTM	9999
190	K2 MOTOR	LCTEMR95TM	9999
191	K2 MOTOR	LCVENT97JMKS	9999
192	K2 MOTOR	LCWRX97JMDP	9999
193	K2 MOTOR	LHCV96	9999
194	K2 MOTOR	LHCV96G	9999
195	K2 MOTOR	LHCV96JM	9999
196	K2 MOTOR	LHCV96JMAPC	9999
197	K2 MOTOR	LHCV99	9999
198	K2 MOTOR	LHCV99G	9999
199	K2 MOTOR	LHCV99JM	9999
200	K2 MOTOR	LHPACD94	9999
201	K2 MOTOR	LHPACD94B	9999
202	K2 MOTOR	LHPACD94JM	9999
203	K2 MOTOR	LHPACD94JMB	9999
204	K2 MOTOR	LHPACD98	9999
205	K2 MOTOR	LHPACD98B	9999
206	K2 MOTOR	LHPACD98JM	9999
207	K2 MOTOR	LHPACD98JMB	9999

208	K2 MOTOR	LHPCV01	9999
209	K2 MOTOR	LHPCV01B	9999
210	K2 MOTOR	LHPCV01JM	9999
211	K2 MOTOR	LHPCV01JMB	9999
212	K2 MOTOR	LHPCV92	9999
213	K2 MOTOR	LHPCV923D	9999
214	K2 MOTOR	LHPCV923DB	9999
215	K2 MOTOR	LHPCV923JM	9999
216	K2 MOTOR	LHPCV92B	9999
217	K2 MOTOR	LHPCV92DJMB	9999
218	K2 MOTOR	LHPCV92JM	9999
219	K2 MOTOR	LHPCV92JMB	9999
220	K2 MOTOR	LHPCV96	9999
221	K2 MOTOR	LHPCV96B	9999
222	K2 MOTOR	LHPCV96JM	9999
223	K2 MOTOR	LHPCV96JMB	9999
224	K2 MOTOR	LHPCV99	9999
225	K2 MOTOR	LHPCV99B	9999
226	K2 MOTOR	LHPCV99JM	9999
227	K2 MOTOR	LHPCV99JMB	9999
228	K2 MOTOR	LHPF15097	9999
229	K2 MOTOR	LHPF150971PC	9999
230	K2 MOTOR	LHPF150971PCJM	9999
231	K2 MOTOR	LHPMST99BYD	9999
232	K2 MOTOR	LHPMST99JMBYD	9999
233	K2 MOTOR	LHPMST99JMD	9999
234	K2 MOTOR	LHPMST99YD	9999
235	K2 MOTOR	LHPMUS94	9999
236	K2 MOTOR	LHPMUS94B	9999
237	K2 MOTOR	LHPMUS94JM	9999
238	K2 MOTOR	LHPMUS94JMB	9999
239	K2 MOTOR	LHPRAM94BYD	9999
240	K2 MOTOR	LHPRAM94JMBYD	9999
241	K2 MOTOR	LHPRAM94JMYD	9999
242	K2 MOTOR	LHPRAM94YD	9999
243	K2 MOTOR	LHPSIV03BHYD	9999
244	K2 MOTOR	LHPSIV03HYD	9999
245	K2 MOTOR	LHPSIV03JMBHYD	9999
246	K2 MOTOR	LHPSIV03JMHYD	9999
247	MINI	COOPER	2002
248	MINI	COOPER	2003
249	MINI	COOPER	2004
250	MINI	COOPER	2005
251	NISSAN	MAXIMA	1995
252	NISSAN	MAXIMA	1996
253	NISSAN	MAXIMA	1997
254	NISSAN	MAXIMA	1998
255	NISSAN	MAXIMA	1999
256	OLDSMOBILE	SILHOUETTE	1997
257	OLDSMOBILE	SILHOUETTE	1998
258	OLDSMOBILE	SILHOUETTE	1999
259	OLDSMOBILE	SILHOUETTE	2000

260	OLDSMOBILE SILHOUETTE	2001
261	OLDSMOBILE SILHOUETTE	2002
262	OLDSMOBILE SILHOUETTE	2003
263	SUBARU IMPREZA	1995
264	SUBARU IMPREZA	1996
265	SUBARU IMPREZA	1997
266	SUBARU IMPREZA	1998
267	SUBARU IMPREZA	1999
268	SUBARU IMPREZA	2000
269	SUBARU IMPREZA	2001
270	TOYOTA CAMRY	1995
271	TOYOTA CAMRY	1996
272	TOYOTA COROLLA	1993
273	TOYOTA COROLLA	1994
274	TOYOTA COROLLA	1995
275	TOYOTA COROLLA	1996
276	TOYOTA COROLLA	1997
277	TOYOTA COROLLA	1998
278	TOYOTA COROLLA	1999
279	TOYOTA COROLLA	2000
280	TOYOTA PICKUP	1989
281	TOYOTA PICKUP	1990
282	TOYOTA PICKUP	1991
283	TOYOTA PICKUP	1992
284	TOYOTA PICKUP	1993
285	TOYOTA PICKUP	1994
286	TOYOTA PICKUP	1995
287	TOYOTA TERCEL	1995
288	TOYOTA TERCEL	1996
289	TOYOTA TERCEL	1997
290	TOYOTA TERCEL	1998
291	TOYOTA TERCEL	1999
292	VOLKSWAGE BEETLE	1998
293	VOLKSWAGE BEETLE	1999
294	VOLKSWAGE BEETLE	2000
295	VOLKSWAGE BEETLE	2001
296	VOLKSWAGE BEETLE	2002